

Case Study - Major Irish Department Store

Problem:

Dirty, faded suspended ceiling tiles over 15 years installed. Light levels low.



Faded ceiling with soot damage around vents

Action:

All fixtures and fittings were covered, the tiles were cleaned and two coats of white Ceilblock was applied by means of an airless spray process. All work was carried out during off peak hours with no need to decommission alarm systems, security cameras, sprinkler systems etc.





The spraying process

The coated ceiling shows a dramatic difference with the grids and air vent also coated, creating a clean, bright working environment.





The client saved 65% compared to replacement costs with a guarantee that the ceiling will retain its new look for as long as a newly fitted ceiling would.

Call Richard on 085 218 9865 or

Click Here To Get A Quotation For Your Premises