



## Case Study - Coffee Shop

### Coffee Shop:

Ceiling dirty and discoloured over time. Air vents, speakers and sprinkler roses also coated.

### Problem:

Faded suspended ceiling tiles. Light levels low.

### Action:

RK Coatings trained crew covered all fixtures & fittings before cleaning the ceiling and applying 2 coats of white CeilBlock CBC110 by means of an airless spray process, during off peak hours.

### Result:

The coated ceiling shows a dramatic difference with the grids, speaker and air vent also coated giving the client a clean, bright working environment.

### Savings:

The client saved 65% compared to replacement costs with a guarantee that the ceiling will retain its new look for as long as a newly fitted ceiling would.



All work was carried out during off peak hours with no need to decommission alarm systems, security cameras, sprinkler systems etc.

Call Richard on 085 218 9865 or  
[Click Here To Get A Quotation For Your Premises](#)